

Metro Public Art Collection Asset Report

Metro Blue Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY18 Action Plan
1	Blue Line Tunnel <i>Thomas Eatherton</i> <i>Unity</i> LED light sculpture installations	1991	NA	Not functioning as intended. Electronic artwork requires refurbishment of 82 lightworks.	FY18 Capital Budget has been requested to replace fiber-optic artwork with new, more efficient LED panels.
2	Wardlow <i>Jacqueline Dreager</i> <i>Great Gathering Place</i> Fiberglass, bronze and steel sculptures; Concrete and steel stools; Glass medallion with imagery	1992	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of gel-coat and wax at fiberglass and bronze elements. Specialized or minor repairs when needed.	Fiberglass artwork sculptural elements are deteriorating.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and apply gel-coat and wax at fiberglass and bronze elements
3	7th Street / Metro Center <i>Joyce Kozloff</i> <i>The Movies: Fantasies and Spectacles</i> Ceramic tile murals	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile is damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal grout.
4	7th Street / Metro Center <i>Roberto Gil de Montes</i> <i>Heaven to Earth</i> Ceramic tile murals	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile is damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal grout.
5	Pico <i>Robin Brailsford</i> <i>Time and Presence</i> Painted steel canopy panels	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of coatings. Specialized or minor repairs when needed.	Paint at artwork panels is fading.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and re-coat panels.
6	San Pedro Street <i>Sandra Rowe</i> <i>Hope, Dream, Path, Focus, Belief</i> Patinated, etched, pigmented waxed bronze panels; stainless steel kinetic sculptures	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of sealant. Specialized or minor repairs when needed.	Paint at artwork panels has faded. Kinetic elements are damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and re-coat panels, repair kinetic elements.
7	Willowbrook / Rosa Parks <i>Joe Sam</i> <i>Hide-n-Seek</i> Painted steel sculpture	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of coatings. Specialized or minor repairs when needed.	Sculptures have sustained pigeon damage and paint has faded.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and re-coat sculptures.
8	Grand / LATT <i>Mark Lere</i> <i>Who, What, Where?</i> Etched and paint filled granite tile paving; etched and paint filled concrete	1994	Completely removed as a result of Blue Line refurbishment Project. CP in place with Artist to replace artwork.	Artwork completely removed during Metro Blue Line Refurbishment Project.	Manage Artist contract to replace artwork. Scheduled completion FY18.
9	Vernon <i>Horace Washington</i> <i>A Tribute to Industry</i> Bronze and powder coated steel stools; galvanized steel benches; stainless steel and painted steel sculpture; ceramic tile	1994	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of sealant. Specialized or minor repairs when needed.	Paint at artwork panels is fading.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and re-coat sculptures, clean and seal grout tile.
10	103rd Street / Watts Towers <i>Roberto Salas</i> <i>Blue Line Totems in Red</i> Painted steel columns; ceramic tile	1994	Partially removed as a result of Blue Line refurbishment Project. CP in place with Artist to replace artwork.	Artwork partially removed during Metro Blue Line Refurbishment Project.	Manage Artist contract to replace artwork. Scheduled completion FY18.

Metro Blue Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY18 Action Plan
11	Pacific Coast Highway <i>Joe Lewis</i> <i>Twelve Principals</i> Ceramic tile medallions	1994	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Artwork medallions require cleaning.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal grout.
12	Anaheim Street Terry Braunstein <i>Local Odysseys</i> Porcelain enamel medallions	1994	Conduct detailed annual artwork inspection and cleaning. Document conditions. Specialized or minor repairs when needed.	Artwork medallions require cleaning.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs and clean.
13	Slauson East Los Streetscapers <i>South Central Suite</i> Porcelain enamel panels; ceramic tile and pigmented concrete and ceramic tile murals	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile is damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal grout.
14	Compton Eva Cockcroft <i>Past, Present and Future</i> Ceramic tile panels; ceramic tile columns	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile is damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal grout.
15	5th Street Jim Isermann <i>Failed Ideals</i> Stain glass medallions	1995	Partially removed as a result of Blue Line refurbishment Project. CP in place with Artist to replace artwork.	Artwork partially removed during Metro Blue Line Refurbishment Project.	Manage Artist contract to replace artwork. Scheduled completion FY18.
16	1st Street Paul Tzanetopoulos <i>Breezy and Delightful</i> Porcelain enamel kinetic medallions	1995	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Artwork medallions require cleaning. Kinetic elements are damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean medallions panels, repair kinetic elements.
17	Downtown Long Beach Patrick Mohr <i>Angel Train</i> Anodized aluminum sculptures	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant and wax. Specialized or minor repairs when needed.	Artwork requires cleaning and application of wax sealant.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and apply sealant and wax.
18	Pacific Ave June Edmonds <i>We Know Who We Are</i> Glass mosaic medallions	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Artwork medallions require cleaning.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and apply sealant to grout.
19	Artesia Lynn Aldrich <i>Blue Line Oasis</i> Stainless steel and ceramic sculpture; glass mosaic tile, painted steel wishing well; glass mosaic panels	1996	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic, glass mosaic panels and sculpture are damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and apply sealant to grout.
20	Washington Elliot Pinkney <i>Running for the Blue Line</i> Painted steel panels; painted columns	1997	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of coatings. Specialized or minor repairs when needed.	Paint has failed at artwork panels. Painted columns incorrectly painted system color.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and re-coat sculptures.
21	Del Amo Colin Gray <i>Del Amo Wheel</i> Glass fiber reinforced concrete sculpture	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Visible graffiti and minor cracking at artwork surface.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and apply sealant.

Metro Blue Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY18 Action Plan
22	7th Street / Metro Center Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Ballast and polycarbonate require replacement.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean, replace polycarbonate facing, replace light bulbs, rotate artwork.
23	7th Street / Metro Center K. Kobayashi, N. Korten & M. Perlas <i>Plantings</i> Pigmented concrete benches; cast aluminum, painted steel, gobos and electrical components	2002	Conduct detailed annual artwork inspection and cleaning. Document conditions. Specialized cleaning of gobos and electrical components, replacement of lighting. Biennial application of sealant. Minor repairs when needed.	All projection units are broken. Electrical is outdated and not functioning as intended. Expo Rail Line impacts altered artwork location.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and apply sealant to grout.
24	Willowbrook / Rosa Parks <i>Michael Massenburg, Robin Strayhorn</i> <i>Pathways To Freedom</i> Glass mosaic, ceramic tile and concrete benches	2002	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Benches are damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and apply sealant to grout.
25	Firestone Ricardo Mendoza <i>The Will to Progress</i> Ceramic tile mural panels	2004	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile is damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal grout.
26	Florence Ricardo Duffy <i>A Florence Moment</i> Ceramic tile murals	2005	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile requires cleaning.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Clean and seal grout.
27	Willow Merge Conceptual Design <i>Out of Sight</i> Glass canopy with laminated imagery, GFRC bench	2006	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of sealant. Specialized or minor repairs when needed.	Bench is damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal.
28	Willowbrook / Rosa Parks Judy Baca <i>Metate Bench</i> GFRC benches with ceramic tile	2008	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of sealant. Specialized or minor repairs when needed.	Bench is damaged.	Perform annual artwork inspections. Document artwork and produce detailed condition and corrective action report. Implement minor repairs, clean and seal.

Metro Red Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY19 Proposed Action Plan
29	Union Station Christopher Sproat <i>Union Chairs</i> Granite benches	1993	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Graffiti etchings at granite benches. Artwork is grimy, in need of cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
30	Union Station Terry Schoonhoven <i>Traveler</i> Ceramic tile mural	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
31	Union Station Cynthia Carlson <i>LA: City of Angels</i> Hand painted mural with reliefs	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of gel-coat and wax at fiberglass and bronze elements. Specialized or minor repairs when needed.	Artwork mural requires lighting.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
32	Civic Center / Grand Park Johnathan Borofsky <i>I Dreamed I Could Fly</i> Hand painted fiberglass sculpture; audio playback system; spotlights	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and software update at audio component. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and lighting replacement. Audio component requires software update.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
33	Pershing Square Stephen Antonakos <i>Neons for Pershing Square</i> Neon sculptures	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of Neon Transformers. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning. Neon transformers are in need of replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
34	Westlake / MacArthur Park Francisco Letelier <i>El Sol/La Luna</i> Ceramic tile murals	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Water intrusion at station at walls impacting Artwork mural. Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
35	Westlake / MacArthur Park Therman Statom <i>Into the Light</i> Glass skylight; acrylic, aluminum, stainless steel and painted steel sculptures; ceramic tile	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and lighting replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
36	Vermont / Santa Monica Robert Millar <i>Untitled</i> Text painted on walls throughout; aluminum and polycarbonate panels; colored lighting	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Lighting component (entrance lighting) is outdated and requires complete renovation. Artwork is grimy, in need of cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
37	Wilshire / Vermont Peter Shire <i>Los Angeles Seen</i> Painted steel and stainless steel sculptures	1996	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Kinetic motorized component not working. Artworks in need of major cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.

Metro Red Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY19 Proposed Action Plan
38	Vermont / Beverly George Stone <i>Untitled</i> Glass fiber reinforced concrete sculptural rock formations	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Artwork is grimy, in need of cleaning and lighting replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
39	Vermont / Sunset Michael Davis <i>Ecliptic/Illume</i> Porcelain, stainless steel, illumination	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Lighting component is not functioning. Artwork is grimy, in need of cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
40	Hollywood / Western May Sun <i>Untitled</i> Painted aluminum and polycarbonate sculptures; lighting; terrazzo and copper paving murals; etched granite; patinated bronze; ceramic tile throughout	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Artwork is grimy, in need of cleaning and lighting replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
41	Hollywood / Vine Gilbert "Magu" Lujan <i>Hooray for Hollywood</i> Painted fiberglass and pigmented concrete benches, hand painted ceramic tiles	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	All platform sculptural elements damaged and removed.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
42	Hollywood / Highland Sheila Klein <i>Underground Girl</i> Painted aluminum fixtures, electrical; aluminum and stainless sculpture	2000	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	Electronic artwork not working. Artwork is grimy, in need of cleaning and lighting replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
43	Universal City / Studio City Margaret Garcia <i>Tree of Califas</i> Carved ceramic tile; stainless steel, painted steel and granite benches; laminated imagery	2000	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
44	North Hollywood Anne Marie Karlsen <i>Kaleidoscope Dreams</i> Ceramic tile	2000	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Artwork is grimy, in need of cleaning and lighting replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
45	7th Street / Metro Center Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Ballast and polycarbonate require replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
46	Vermont / Beverly Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Ballast and polycarbonate require replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.

Metro Red Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY19 Proposed Action Plan
47	Hollywood / Highland Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Ballast and polycarbonate require replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
48	Universal City / Studio City Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Ballast and polycarbonate require replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
49	7th Street / Metro Center K. Kobayashi, N. Korten & M. Perlas <i>Plantings</i> Pigmented concrete benches; cast aluminum, painted steel, gobos and electrical components	2002	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Ballast and polycarbonate require replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
50	Civic Center / Grand Park Peter Requam <i>Civic Center Benches</i> Granite benches	2004	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Graffiti etchings at granite benches. Artwork is grimy, in need of cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
51	Civic Center / Grand Park Samm Kunce <i>In the Living Rock</i> Glass mosaic and granite murals	2004	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Graffiti etchings at granite artwork. Artwork is grimy, in need of cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
52	Vermont / Santa Monica George Legrady <i>Kinetic Flow</i> Porcelain enamel mural	2006	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Minor damage at artwork face. Artwork is grimy, in need of cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
53	Civic Center Station Faith Ringgold <i>People Portraits: in Creativity, Performing, Sports & Fashion</i> Glass mosaic panels	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
54	Westlake / MacArthur Park Sonia Romero <i>MacArthur Park, Urban Oasis</i> Hand carved porcelain mosaic panels	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Water intrusion at station at walls impacting Artwork mural. Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
55	Vermont / Beverly Tyree Guyton <i>People in Motion</i> Glass mosaic mural	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
56	Universal City / Studio City Stephen Johnson <i>Untitled</i> Glass mosaic mural	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.

Metro Red/Purple Line						
	Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY19 Proposed Action Plan
57	Wilshire / Normandie	Frank Romero <i>Festival of Masks Parade</i> Painted aluminum mural	1996	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
58	Wilshire / Western	Richard Wyatt <i>People Coming People Going</i> Ceramic tile murals	1996	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
59	Wilshire / Normandie	Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Ballast and polycarbonate require replacement.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
60	Wilshire / Western	Pae White <i>The Beppins</i> Pigmented concrete stools; seeded lithocrete paving	2003	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is grimy, in need of cleaning and sealant.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.
61	Wilshire / Vermont	Bob Zoell <i>No Title</i> Ceramic tile murals	2004	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Broken tile and graffiti etchings at granite artwork. Artwork is grimy, in need of repair and cleaning.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Red Line art assets.

Metro Green Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY21 Proposed Action Plan
62	Redondo Beach Carl Cheng <i>The Museum of Space Information</i> Painted steel satellite towers and satellite; painted steel TV Monitor cabinets and monitors; painted steel, glass and mixed media windscreens, concrete, glass, stone and stainless steel benches; concrete and resin planet formations; glass and mixed media illuminated diorama; glass, stone and steel inlays; porcelain enamel mural	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Structural elements appear in poor condition, damaged, artwork satellite feed not working. Currently with Metro Engineering for review. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
63	Douglas Renee Petropoulos <i>Untitled</i> Painted steel medallions; painted steel and galvanized steel tower, painted steel fencing; painted steel and concrete stools and benches; bronze inlays; bronze and painted steel telescopes; anodized aluminum panels; stamped text in concrete; porcelain enamels murals; terrazzo and bronze mural paving; ceramic tiles; glass with laminated imagery	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Sculpted artwork medallions appear damaged. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
64	El Segundo Daniel J. Martinez <i>For Your Intellectual Entertainment</i> Painted steel and galvanized steel structures, painted steel fencing; painted steel and concrete stools and benches; bronze inlays; bronze and painted steel telescopes; clocks; stamped text in concrete; porcelain enamels murals; terrazzo and bronze mural paving	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork electronic element not working. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
65	Mariposa Charles Dickson <i>Divine Order: the Manifestation of the Soaring Spirit</i> Painted, pigmented concrete benches; ceramic tiles; glass and laminated imagery; terrazzo and bronze mural paving; ceramic tile cutouts; concrete relief mural; ceramic tile columns	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Broken glass windscreen removed from the platform in the Winter of 2016 .Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
66	Aviation / LAX Richard Turner <i>Untitled</i> Glass and laminated imagery; terrazzo and bronze mural paving; pigmented concrete and steel chairs, tables and benches; painted steel panels	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork sculptures require paint touch up, minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
67	Hawthorne / Lennox Mineko Grimmer <i>Companions</i> Patinated bronze sculptures; black granite benches	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Etchings at granite benches. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.

Metro Green Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY21 Proposed Action Plan
68	Crenshaw Buzz Spector <i>Crenshaw Stories</i> Ceramic tile murals; concrete benches; terra cotta tile paving; concrete impressions	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor damage at artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
69	Vermont / Athens Kim Yasuda <i>Real Green</i> Ceramic tile murals; terrazzo and bronze mural paving; painted steel and wood benches; wood, painted aluminum and steel sculptural buckets	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor cracking at artwork terrazzo paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
70	Harbor Fwy Steve Appleton <i>Locus: City Imprints</i> Granite benches; pigmented concrete and steel benches; glass fiber reinforced concrete sculptures; pigmented concrete mural paving	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork sculpture vandalized. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
71	Avalon Willie Middlebrook <i>Portrait of My People #619</i> Porcelain enamel murals	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork sculpture vandalized. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
72	Avalon John Outterbridge <i>Pyramid</i> Concrete and ceramic tile sculptures; pigmented concrete mural paving	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork sculpture vandalized. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
73	Avalon Stanley C. Wilson <i>Bridge of Culture</i> Pigmented and ceramic tile benches; ceramic tile mural paving, painted steel panels	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork vandalized. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
74	Long Beach Blvd Sally Weber <i>Celestial Chance</i> Terra cotta tile mural paving; pigmented concrete and steel paving, painted steel sculptures; perforated steel and acrylic sculpture	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor damage at artwork paving. Painted elements have faded. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.
75	Lakewood Blvd Erika Rothenberg <i>Wall of (Un)Fame</i> Pigmented concrete panels; pigmented concrete benches; pigmented concrete receptacles; painted steel grills; bronze plaque	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artworks vandalized. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.

Metro Green Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY21 Proposed Action Plan
76	Norwalk Meg Cranston <i>Suka: Place of Bees</i> Ceramic tile; bronze tile; painted stainless steel sculptures; laminated imagery; painted steel and fiberglass sculptures	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor damage at artwork paving. Painted elements have faded. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Green Line art assets.

Metro Gold Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY23 Proposed Action Plan
77	Chinatown Chusien Chang <i>The Wheels of Change</i> Painted aluminum benches; etched granite, glass and stainless steel compass; bronze bell; etched granite tile pavers	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Benches are etched (vandalized), require painting. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
78	Lincoln / Cypress Cheri Gualke <i>Water Street: River of Dreams</i> Patinated copper, lexan and stainless steel panels; patinated bronze sculpture; stone boulders and seeded glass arroyo; concrete impressions	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is etched (vandalized), require patina and wax. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
79	Heritage Square Roberto L. Delgado <i>El Quetzalcoatl de Xochicalco and La Gente del Pueblo</i> Ceramic tile paving; carved volcanic stone sculpture with rebar attachments	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor damage at artwork paving. Painted elements have faded. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
80	Southwest Museum Teddy Sandoval <i>Highland Park Gateway</i> Glass fiber reinforced concrete and ceramic tile benches; glass fiber reinforced concrete, aluminum and glass mosaic sculptures; painted steel chairs; glass seeded arroyo paving	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor damage at artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
81	Highland Park Jud Fine <i>Stone Tree Inverted Post (Bound Water Light)</i> Pigmented illuminated acrylic domes; concrete benches; pigmented glass fiber reinforced concrete and bronze sculpture	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is etched (vandalized), require patina and wax. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
82	South Pasadena Michael Stutz <i>Astride-Aside</i> Patinated bronze, painted steel sculpture; stone pedestals	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is etched (vandalized), require patina and wax. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.

Metro Gold Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY23 Proposed Action Plan
83	Fillmore Michael C. McMillen <i>Geologica 42</i> Patinated bronze sculptures	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is etched (vandalized), require patina and wax. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
84	Del Mar Ries Niemi <i>Kinetic Energy</i> Stainless steel fencing	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor damage at artwork fencing. Painted elements have faded. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
85	Memorial Park John Valadez <i>The First Artist in Southern California: A Short Story</i> Painted steel sculpture	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is fading. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
86	Lake Pat Ward Williams <i>Everyday People</i> Laminated imagery within glass panels	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork panel damaged and removed. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
87	Allen Michael Amescua <i>Rider's Dream</i> Stainless steel sculpture; glazed terra cotta paving; painted steel and stainless steel panels	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is fading. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
88	Sierra Madre Villa Tony Gleaton <i>Untitled</i> Porcelain enamel panels	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is fading. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
89	Sierra Madre Villa Beth Thielen <i>Images of Commonality / Nature and Movement</i> Concrete reliefs; glass mosaic and concrete mural paving; painted steel, acrylic and electrical light box	2003	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is etched (vandalized), require paint and renovation. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
90	Union Station Roy Nicholson <i>Solar Shift: San Bernardino and Santa Monica</i> Glass mosaic murals, painted walls	2006	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.

Metro Gold Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY23 Proposed Action Plan
91	Little Tokyo / Arts District Hirokazu Kosaka <i>Buffer Zone</i> Granite benches	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Etching at artwork granite (vandalism). Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
92	Pico / Aliso Rob Nielson <i>About Place About Face</i> Cast iron sculptures	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is rusting. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
93	Mariachi Plaza Alejandro de la Loza <i>El Nino Perdido</i> Cast bronze sculptures; granite panels	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is etched (vandalized), requires minor repairs and waxing. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
94	Soto Nobuho Nagasawa <i>Landings</i> Aluminum panels of imagery and text; Glass curtain wall; Stainless steel, acrylic and LED sculpture	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is grimy and lighting is out. In need of cleaning and sealant. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
95	Indiana Paul Botello <i>Syncretic Manifestations</i> Stainless steel panels	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
96	Maravilla Jose Lopez <i>Maravilla Hearts of Tokens</i> Stainless steel sculptures; aluminum panels	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
97	East LA Civic Center Clement Hanami <i>Through the Looking Glass or Traveling at the Speed of Light (Rail)</i> Painted steel sculpture; pigmented concrete paving	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
98	Atlantic Adobe LA <i>Blissful Interiors</i> Painted steel sculpture; GFRC pigmented benches; ceramic tile paving	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.

Metro Gold Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	FY23 Proposed Action Plan
99	Arcadia Michael Davis <i>Arcadian Zephyr</i> Perforated stainless steel panels, painted steel and kinetic bronze weathervane, etched granite bench backs, glass canopy. Lithocrete paving at adjacent parking garage.	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
100	Monrovia Cha-Rie Tang <i>River of Time</i> Hard carved ceramic tiles at platform paving and columns. Hand carved ceramic tiles at adjacent parking garage.	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
101	Duarte / City of Hope Andrea Myklebust and Stanton Gray Sears <i>Spirit of the San Gabriel River</i> Sculptural painted steel and stone columns, bronze pavers at platform.	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
102	Inwindale Robin Brailsford <i>Pioneros De La Rivera De San Gabriel</i> Painted steel panels and lithocrete pavers at platform. Lithocrete pavers at adjacent parking garage.	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
103	Azusa Downtown Jose Antonio Aguirre <i>A Passage Through Memory</i> Glass fiber reinforced concrete entrance portals with painted steel and glass mosaic. Glass mosaic at columns.	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.
104	APU/Citrus College Lynn Goodpasture <i>Azusa Horticultural Paradise</i> Mosaic glass murals at benches, glass canopy. Etched concrete at adjacent parking garage.	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Perform detailed annual artwork inspection and documentation, develop a condition and corrective action report, and manage implementation of specialized cleaning, repairs and conservation. Will require new FTE to manage Gold Line art assets.

Metro Orange Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
105	Alignment Jud Fine <i>Seven Spots and a Path</i> Alignments landscaping	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
106	North Hollywood Caryl Davis <i>Dramatic Local</i> Porcelain enamel steel panel; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Abatement film at artwork panel requires replacement, minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Orange Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
107	Laurel Canyon Phung Huynh <i>Lucky California</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
108	Valley College Laura London <i>Former Location/Contemporary Portrait</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
109	Valley College, Van Nuys, Sepulveda, Balboa, Reseda Renee Petropoulos <i>14 Miles</i> Terrazzo benches	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor cracking / chipping at terrazzo artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
110	Woodman Daniel Marlos <i>Journey to California</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
111	Van Nuys Roxene Rockwell <i>VAN NUYS, The New Town</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
112	Sepulveda Michele Martinez <i>Todos Vuelven</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
113	Woodley John Roloff <i>Valley Scan</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Orange Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan	
114	Balboa	John O'Brien <i>OverSite</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
115	Reseda	Jody Zellen <i>Now and Then</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
116	Tampa	Sandow Birk <i>Tarzan and Tarzana</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
117	Pierce College	Pat Warner <i>What We See</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
118	De Soto	John Divola <i>Images From Dogs Chasing My Car in the Desert</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
119	Canoga	Roy Dowell <i>Constructed Histories</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism). Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
120	Canoga	Ken Gonzales-Day <i>Western Imaginary</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism). Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Orange Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
121	Sherman Way Margaret Lazzari <i>Ovensmouth / Canoga Park</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism). Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
122	Roscoe Sam Erenberg <i>Liquid Light: Flowing Into The Future</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism). Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
123	Nordhoff Anne Marie Karlsen <i>Strati</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism). Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
124	Chatsworth Lisa Adams <i>A Glimpse of Stoney Point</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Minor etching at artwork panels (vandalism). Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Expo Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
125	LATTC / Ortho Institute Christofer C. Dierdorff <i>The Intimacy of Place</i> Porcelain enamel steel panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
126	Jefferson / USC Samuel Rodriguez <i>Urban Dualities</i> Hand-glazed, hand-cut ceramic mosaic pane	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Expo Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
127	Expo Park / USC Robbert Flick <i>On Saturdays</i> Photographic porcelain tile panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
128	Expo / Vermont Jessica Polzin McCoy <i>Neighborhood Portrait: Reconstructed</i> Hand-glazed, hand-cut ceramic mosaic panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
129	Expo / Western Ronald J. Llanos <i>Ephemeral Views: A Visual Essay</i> Hand-glazed, hand-cut ceramic mosaic panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
130	Expo / Crenshaw Willie Robert Middlebrook Jr. <i>Wanderers</i> Glass mosaic panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
131	Farmdale Michael Massenburg <i>All in a Day</i> Glass mosaic panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
132	Expo / La Brea Jose Lozano <i>LA Metro Loteria</i> Commercial tile, ink sublimation panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
133	La Cienega / Jefferson Daniel Gonzales <i>Engraved in Memory</i> Hand-glazed, hand-cut ceramic porcelain mosaic panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Expo Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
134	Culver City Tom LaDuke <i>Unknowable Origins</i> Glass mosaic panels	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
135	Palms Shizu Saldamando <i>Artist Educators</i> Glass mosaic and hand-cut ceramic mosaic panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Failed paint system on Expo 1 station structures may compromise artwork. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
136	Westwood / Rancho park Abel Alejandro <i>Panoramas</i> Photographic porcelain tile panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
137	Expo / Sepulveda Susan Logoreci <i>Right Above the Right-of-Way</i> Hand-glazed, hand-cut ceramic mosaic panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
138	Expo / Bundy Nzuji de Magalhães <i>And Here I Will Stay</i> Glass mosaic and hand-cut ceramic mosaic panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
139	26th St / Bergamot Constance Mallinson <i>Local Color</i> Photographic porcelain tile panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
140	17th St / SMC Carmen Argote <i>What you wore, What you wear</i> Photographic porcelain tile panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
141	Downtown Santa Monica Judithe Hernández <i>L.A. Sonata</i> Glass mosaic panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Silver Line					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
142	Cal State LA Merge Conceptual Design <i>Overcoat - CSULA</i> Painted steel; painted concrete; Ceramic tile	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
143	LAC + USC Medical Center Merge Conceptual Design <i>Untitled</i> Painted steel; painted concrete; Ceramic tile	2009	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
144	El Monte Transit Center Donald Lipski <i>Time Piece</i> Stainless steel sculpture; painted steel and electronic sculpture	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Corrosion present. Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
145	Harbor Gateway Transit Center Alison Saar <i>Paraje</i> Stainless steel sculpture	2012	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Corrosion present. Artwork inspection and condition report required. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
146	El Monte Transit Center Eloy Torrez <i>The Steps We Take</i> Powder coated sublimation murals	2014	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
147	El Monte Transit Center Martin Durazo <i>Vamos Juntos/Juntas</i> Powder coated sublimation murals	2014	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
148	El Monte Transit Center Phung Huynh <i>In The Meadow</i> Powder coated sublimation murals	2014	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
149	El Monte Transit Center Vincent Ramos <i>El Monte Legion Stadium</i> Powder coated sublimation murals	2014	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Facilities					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
150	Union Station: Gateway Transit Center James Doolin <i>Los Angeles Circa 1870, 1910, 1950 and after 2000</i> Painted murals	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
151	Union Station: Gateway Transit Center Margaret Nielsen <i>LA Dialogs</i> Painted mural	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
152	Union Station: Gateway Transit Center Patrick Nagatani <i>Epoch</i> Painted mural	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
153	Union Station: Gateway Transit Center May Sun and Richard Wyatt <i>City of Dreams, River of History</i> Pigmented concrete, glass, steel and ceramic tile fountain; stone, patinated bronze paving; ceramic tile	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Water issues at soffit. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
154	Union Station: Gateway Transit Center Richard Wyatt <i>City of Dreams, River of History</i> Painted mural	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is dirty. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
155	Union Station: Gateway Transit Center Bill Bell <i>A Train</i> LED light sticks, audio and video components	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
156	Union Station: Gateway Transit Center East Los Streetscapers <i>La Sombra del Arroyo</i> Painted bronze sculpture; ceramic tile; stone tile	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
157	Union Station: Gateway Transit Center Kim Yausda & Noel Korten <i>ReUnion</i> Stainless steel, glass and copper bus shelters	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Broken glass panel. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
158	Union Station: Gateway Transit Center Michael Amescua <i>Guardians of the Track</i> Painted steel panels; anodized aluminum panels	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork is in need of corrosion mitigation, cleaning and paint. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.

Metro Facilities					
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition Status	Action Plan
159	Union Station: Gateway Transit Center Peter Shire <i>Paseo Cesar Chavez</i> Fountain, ceramic tile benches	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
160	Union Station: Gateway Transit Center Elsa Flores <i>Paseo Cesar Chavez</i> Fountain, ceramic tile benches	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
161	Union Station: Gateway Transit Center Roberto Gil de Montes <i>Paseo Cesar Chavez</i> Fountain, ceramic tile benches	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
162	Union Station Passageway Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork requires new polycarbonate sheeting. Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
163	Metro Customer Service Center (former) Jim Isermann <i>Untitled (Tilfords)</i> Powder coated aluminum panels	2006	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Artwork removed as part of Purple Line Extension. Artwork to be relocated /re-purposed.	Will request dedicated staff and resources in future years.
164	Division 9 Facility Raul de la Sota <i>Forward to the Past</i> Painted honey comb aluminum mural	2007	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
165	Division 9 Facility Mark Lere <i>The Metro Machine</i> Terrazzo mural paving	2007	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
166	Division 24 Facility Christine Beniston <i>Field of Poppies</i> Powder coated steel laced into fencing	2015	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
167	Division 13 Facility Christine Ulke <i>El Aliso de Los Angeles</i> Illuminated polycarbonate panels with graphic PVB film layers, LEDs	2015	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.
168	Union Station: Gateway Transit Center and Pedestrian Drop Off Area (POV) Michael Amescua <i>Guardians of the Rail</i> Painted steel panels; Painted aluminum panels	2016	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Will require resources to perform artwork inspections and condition report. In addition, possible professional conservator report identifying recommendations, as well as implementation of specialized cleaning, repairs and conservation.	Will request dedicated staff and resources in future years.