PROCUREMENT SUMMARY

METRO EXPRESSLANES PROGRAM MANAGEMENT SUPPORT

AE275020011497

1.	Contract Number: AE275020011497				
2.	Contractor: WSP USA, Inc. (formerly Parsons Brinckerhoff, Inc.)				
3.	Mod. Work Description: Additional planning studies and Geotechnical				
	reports; 30% design plans and estimate, traffic modeling				
	·				
4.	Contract Work Description: ExpressLanes Program Management				
	Support				
5.	The following data is current as of: September 12, 2019				
6.	Contract Complet	ion Status	Financial Status		
		00/05/00/5		AT TOO OOO	
	Contract	06/25/2015	Contract Award	\$7,700,000	
	Awarded:	00/05/0045	Amount:	Ф 77 0 000	
	Notice to	06/25/2015	Total of Modifications	\$770,000	
	Proceed (NTP):		Approved:		
	Original	09/13/2018	Pending	\$5,677,001	
	Complete	00/10/2010	Modifications	Ψο,ονν,οον	
	Date:		(including this		
			action):		
	Current Est.	09/13/2023	Current	\$14,147,001	
	Complete Date:		Contract Value		
			(with this		
			action):		
7.	Contract Administ	trator:	Telephone Number:		
	Leisa Oden-Kurz		213.922.2790		
8.	Project Manager:		Telephone Number:		
	Philbert Wong		213.418.3137		

A. Procurement Background

This Board Action is to approve Contract Modification No. 7 issued to continue program management support services for a Project Approval/Environmental Document (PA/ED) and 30% design for the Interstate 105 ExpressLanes project.

This Contract Modification will be processed in accordance with Metro's Acquisition Policy and the contract type is a firm fixed price.

On June 25, 2015, the Board awarded a 36-month, firm fixed price Contract No. AE275020011497 to WSP USA, Inc. (formerly Parsons Brinckerhoff, Inc.) for ExpressLanes Program Management Support Services in the amount of \$7,700,000.

B. Cost Analysis

The recommended price has been determined to be fair and reasonable based upon the technical analysis, independent cost estimate (ICE), cost analysis and fact finding of the work to be performed.

Proposal Amount	Metro ICE	Negotiated Amount
\$5,677,001	\$5,910,381	\$5,677,001

Refer to Attachment B – Contact Modification /Change Order Log.